

DART AEROSPACE LTD	Work Order :	22114
	Description:	Inspection
	Approval :	
		Page 1 of 1

Step	Location	Procedure	By	Date																				
1	PK	<p>Remove from Stock Yes/No Return# <u>314</u></p> <table> <thead> <tr> <th>Qty</th> <th>Part Number</th> <th>Description</th> <th>Batch</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>02665-1</td> <td>C</td> <td>1320214-</td> </tr> <tr> <td>1</td> <td>02665-2</td> <td>Jackets</td> <td>1320215-</td> </tr> <tr> <td>1</td> <td>02666-1</td> <td></td> <td>1320216-</td> </tr> <tr> <td>1</td> <td>02666-2</td> <td></td> <td>1320217-</td> </tr> </tbody> </table>	Qty	Part Number	Description	Batch	1	02665-1	C	1320214-	1	02665-2	Jackets	1320215-	1	02666-1		1320216-	1	02666-2		1320217-		
Qty	Part Number	Description	Batch																					
1	02665-1	C	1320214-																					
1	02665-2	Jackets	1320215-																					
1	02666-1		1320216-																					
1	02666-2		1320217-																					
2		<p>Re-work/Inspection:</p> <p>FP Touchup as per RS 1004</p> <p>QC3 Inspect level 3</p> <p>ST Return to stock Identify & Stock</p>	M CL CL	05/01/10 05/01/11 05/01/11																				
3	PK	Identify & Stock:																						
	DC	<p>Close W/O Inspect Level 21</p>	17.51 JKC	05-01-12 05.01.12																				